



ISO 14001 CERTIFIED  
September 29, 2010

Via Certified Mail

Dr. Susan Hedman  
Regional Administrator  
U.S. Environmental Protection Agency  
Region 5 (R-19J)  
77 W. Jackson Boulevard  
Chicago, Illinois 60604-3590

EPA Region 5 Records Ctr.



376086

and

Commissioner Thomas Easterly  
Indiana Department of Environmental Management  
100 N. Senate Avenue  
Indianapolis, Indiana 46204

Re: ESI Environmental, Inc's TSCA PCB Application Letter  
Pursuant to 40 CFR 761.61(c) and (a)(5)


Dear Regional Administrator Hedman and Commissioner Easterly:

This letter is being submitted on behalf of ESI Environmental, Inc. ("ESI"), the owner of the facility located at 4910 West 86<sup>th</sup> Street, Indianapolis, Indiana (the "Facility"), and WSP Environment & Energy ("WSP"), the contractor who will perform and/or oversee the performance of the PCB decontamination work at the Facility. ESI and WSP have been working with Mr. Tony Martig, Ms. Karen Kirchner, and Mr. John Steketee of EPA, Region 5, and Mr. George Richotte of the Indiana Department of Environmental Management ("IDEM") to address PCB contamination that came to be located at the Facility due to ESI's unknowing processing of PCB contaminated oily wastes. In furtherance of those efforts, WSP submitted a Revised Tank 51 Restoration Work Plan Application to Mr. Martig on July 7, 2010 ("the Work Plan") on behalf of ESI and Chartis Specialty Lines Insurance Company, the insurance company that will pay for the decontamination activities set forth in the Work Plan. EPA, Region 5, staff have reviewed that Work Plan and informed ESI that this letter must be submitted prior to approving the Work Plan. A copy of the Work Plan is attached.

The attached Work Plan contains the information required by 40 CFR 761.61(a)(3) except for the certification required by 40 CFR 761.61(a)(3)(E). Therefore, the following is the required certification:


ESI and WSP certify that all sampling plans, sample collection procedures, sample preparation procedures, extraction procedures, and instrumental/chemical analysis procedures used to assess or characterize the PCB contamination at the cleanup site, are on file at WSP Environment & Energy, 11190 Sunrise Valley Drive, Suite 300, Reston, Virginia, 20191, and are available for EPA inspection.

If you have any questions, please contact Dave McLay, WSP, at (303) 850-9200.



Thomas Gawlik  
President and CEO  
ESI Environmental, Inc.

Sincerely,



David S McLay, P.E.  
Technical Manager  
WSP Environment & Energy

Attachment

cc: John Steketee, Esq., Office of Regional Counsel, EPA Region 5 (via electronic mail w/ attachment)  
Karen Kirchner, EPA Region 5 (via electronic mail w/ attachment)  
George Richotte, IDEM (via electronic mail w/ attachment)  
Christopher Ferragamo, Esq., Jackson & Campbell (via electronic mail w/ attachment)